

# WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

AA38378



6MTH

164-190 Cleveland Street  
Birkenhead, Merseyside  
CH41 3QQ

Tel: 0151-647 5131

Fax: 0151-666 2631

## MOT REPORT

Test Centre No. 43339

Reg. No. <b>X696 HNA</b>	Make/Model <b>Ford Mondeo cc</b>	Year of Manufacture <b>99</b>	Class of Vehicle PH <input checked="" type="checkbox"/> III <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>
VIN or Chassis <b>WFO5XXGBJSYS74467</b>	Recorded Mileage <b>196689</b>	Colour <b>Maroon</b>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
<b>Lighting Equipment</b>				<b>PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED</b>
Front & Rear Lamps	1/1	/		
Headlamps	1/2	/		
Headlamp Aim	1/6	/		
Stop Lamps	1/3	/		
Rear Reflectors	1/4	/		
Direction Indicators	1/5	/		

Steering & Suspension	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Steering Control	II/1	/		No: 43339 <b>ALF WALSH AUTO ENG'R LTD</b> CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625
Steering Mechanism/system	II/2	/		
Power Steering	II/8	/		
Transmission Shafts	II/2,4,9	/		
Wheel Bearings	II/4	/		
Front Suspension	II/5-9	/		
Rear Suspension	II/9	/		
Shock Absorbers	II/10	/		
Wheel Alignment	N/A	/		

Brakes	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Controls	III/1,3	/		<b>W.B.C. VEHICLE PASS</b>
Condition of Service Brake System	III/3,4	/		
Condition of Parking Brake System	III/1,2	/		
Service Brake Performance	III/5,8	/		
Parking Brake Performance	III/5,8	/		

Tyres & Wheels	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Tyre Type	IV/1	/		<b>P/H A/C</b>
Tyre Load/Speed Rating (Class VII)		/		
Tyre Condition	IV/1	/		
Road Wheels	IV/2	/		

Seat Belts	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Mountings	V/1	/		<b>P/H A/C</b>
Condition	V/1	/		
Operation	V/1	/		

Vehicle Weight	N/S	O/S	Totals	Balance	Requirement	% Efficient
Brake Efficiency						
Front Brakes	273	321	4	4	50	74
Rear Brakes	270	270				
Hand Brake	383	260				

General	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Windscreen Wipers & Washers	VI/1,2	/		<b>W.B.C. VEHICLE PASS</b>
Horn	VI/4	/		
Exhaust System	VI/3	/		
Registration No./VIN No.		/		
Vehicle Structure	VI/5	/		
View of Road		/		

<table border="1"> <thead> <tr> <th>Reading</th> <th>Pass</th> <th>Fail</th> </tr> </thead> <tbody> <tr> <td>CO</td> <td></td> <td></td> </tr> <tr> <td>HC</td> <td></td> <td></td> </tr> </tbody> </table>	Reading	Pass	Fail	CO			HC			I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due. Customer's signature..... Date of test..... <b>26.10.09</b> Tester's signature..... <i>[Signature]</i>	Customer's name..... <b>D Redfern</b> Customer's address..... <b>7A Larkwood Lane, Penrhy, CH41 6YH</b> Tel. no.....
Reading	Pass	Fail									
CO											
HC											
<table border="1"> <thead> <tr> <th>Reading</th> <th>Pass</th> <th>Fail</th> </tr> </thead> <tbody> <tr> <td>CO</td> <td></td> <td></td> </tr> <tr> <td>HC</td> <td></td> <td></td> </tr> </tbody> </table>	Reading	Pass	Fail	CO			HC				
Reading	Pass	Fail									
CO											
HC											