


# WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE



6 MSA  
164-190 Cleveland Street  
Birkenhead, Merseyside  
CH41 3QQ  
Tel: 0151-647 5131  
Fax: 0151-666 2631

## MOT REPORT

Test Centre No. 43339

Reg. No. <b>X729TUA</b>	Make/Model <b>PEUGEOT 407</b>	Year of Manufacture <b>2000</b>	Class of Vehicle PH <input type="checkbox"/> III <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>
VIN or Chassis No. <b>NF38B2H2F812S3743</b>	Registered Mileage <b>189478</b>	Colour <b>BLACK</b>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
<b>Lighting Equipment</b>				
Front & Rear Lamps	1/1	-		<b>PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED</b>
Headlamps	1/2	-		
Headlamp Aim	1/6	-		
Stop Lamps	1/3	-		
Rear Reflectors	1/4	-		
Direction Indicators	1/5	-		
<b>Steering &amp; Suspension</b>				
Steering Control	II/1	-		
Steering Mechanism/system	II/2	-		
Power Steering	II/3	-		
Transmission Shafts	II/2,4,9	-		
Wheel Bearings	II/4	-		
Front Suspension	II/5-9	-		
Rear Suspension	II/9	-		
Shock Absorbers	II/10	-		
Wheel Alignment	N/A	<b>OK</b>		
<b>Brakes</b>				
Controls	III/1,3	-		
Condition of Service Brake System	III/3,4	-		
Condition of Parking Brake System	III/1,2	-		
Service Brake Performance	III/5,8	-		
Parking Brake Performance	III/5,8	-		
<b>Tyres &amp; Wheels</b>				
Tyre Type	IV/1	-		
Tyre Load/Speed Rating (Class VII)		<b>N/A</b>		
Tyre Condition	IV/1	-		
Road Wheels	IV/2	-		
<b>Seat Belts</b>				
Mountings	V/1	-		
Condition	V/1	-		
Operation	V/1	-		

No: 43339  
ALF WALSH AUTO ENG'R LT  
CLEVELAND ST./POOL ST.  
BIRKENHEAD  
Tel: 0151 666 6625

### W.B.C. VEHICLE PASS

Vehicle Weight	N/S	O/S	Totals	Balance	Requirement	% Efficient
<b>Brake Efficiency</b>						
Front Brakes						
Rear Brakes						
Hand Brake						
<b>General</b>						
Windscreen Wipers & Washers	VI/1,2	-				
Horn	VI/4	-				
Exhaust System	VI/3	-				
Registration No./VIN No.		-				
Vehicle Structure	VI/5	-				
View of Road		-				

<table border="1"> <tr> <th colspan="3">Petrol Exhaust Emissions</th> </tr> <tr> <td>Reading</td> <td>Pass</td> <td>Fail</td> </tr> <tr> <td>CO</td> <td></td> <td></td> </tr> <tr> <td>HC</td> <td></td> <td></td> </tr> </table>	Petrol Exhaust Emissions			Reading	Pass	Fail	CO			HC			<p>I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.</p> <p>Customer's signature: <i>[Signature]</i></p> <p>Date of test: <b>03/08/08</b></p> <p>Tester's signature: <i>[Signature]</i></p>	<p>Customer's name: <b>W S PIERCY</b></p> <p>Customer's address: <b>37 BOSWELL RD PRENTON WIRRAL</b></p> <p>CH43 30Q</p> <p>Tel. no: <b>0151 608 8921</b></p>
Petrol Exhaust Emissions														
Reading	Pass	Fail												
CO														
HC														
<table border="1"> <tr> <th colspan="3">Diesel Exhaust Emissions</th> </tr> <tr> <td>Reading</td> <td>Pass</td> <td>Fail</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>	Diesel Exhaust Emissions			Reading	Pass	Fail								
Diesel Exhaust Emissions														
Reading	Pass	Fail												