

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

Cert No. **WA383440**



164-190 Cleveland Street
 Birkenhead, Merseyside
 CH41 3QQ
 Tel: 0151-647 5131
 Fax: 0151-666 2631

MOT REPORT

6 Months Test 12 Months Test

Plate No. **947**

Reg. No. Y799 EPR	Make/Model Citroen Picasso cc	Year of Manufacture 2000	Class of Vehicle PH <input type="checkbox"/> H <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>
VIN or Chassis VF7KHNFVJ38991205	Recorded Mileage 145624	Colour Silver	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only			
Lighting Equipment							
PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED							
Front & Rear Lamps	1/1	<input checked="" type="checkbox"/>					
Headlamps	1/2	<input checked="" type="checkbox"/>					
Headlamp Aim	1/6	<input checked="" type="checkbox"/>					
Stop Lamps	1/3	<input checked="" type="checkbox"/>					
Rear Refractors	1/4	<input checked="" type="checkbox"/>					
Direction Indicators	1/5	<input checked="" type="checkbox"/>					
Steering & Suspension							
Steering Control	II/1	<input checked="" type="checkbox"/>					
Steering Mechanism/system	II/2	<input checked="" type="checkbox"/>					
Power Steering	II/3	<input checked="" type="checkbox"/>					
Transmission Shafts	II/2,4,9	<input checked="" type="checkbox"/>					
Wheel Bearings	II/4	<input checked="" type="checkbox"/>					
Front Suspension	II/5-9	<input checked="" type="checkbox"/>					
Rear Suspension	II/9	<input checked="" type="checkbox"/>					
Shock Absorbers	II/10	<input checked="" type="checkbox"/>					
Wheel Alignment	N/A	<input checked="" type="checkbox"/>					
Brakes							
Controls	III/1,3	<input checked="" type="checkbox"/>					
Condition of Service Brake System	III/3,4	<input checked="" type="checkbox"/>					
Condition of Parking Brake System	III/1,2	<input checked="" type="checkbox"/>					
Service Brake Performance	III/5,8	<input checked="" type="checkbox"/>					
Parking Brake Performance	III/5,8	<input checked="" type="checkbox"/>					
Tyres & Wheels							
Tyre Type	IV/1	<input checked="" type="checkbox"/>					
Tyre Load/Speed Rating (Class VII)		<input checked="" type="checkbox"/>					
Tyre Condition	V/1	<input checked="" type="checkbox"/>					
Road Wheels	V/2	<input checked="" type="checkbox"/>					
Seat Belts							
Mountings	V/1	<input checked="" type="checkbox"/>					
Condition	V/1	<input checked="" type="checkbox"/>					
Operation	V/1	<input checked="" type="checkbox"/>					
Vehicle Weight							
		N/S	O/S	Totals	Balance	Requirement	% Efficient
Brake Efficiency		Front Brakes	518	474			
		Rear Brakes	95	102			
		Hand Brake	377	182			
					PHH	A/D	81
						16 x	38
General							
Windscreen Wipers & Washers	VI/2	<input checked="" type="checkbox"/>					
Horn	VI/4	<input checked="" type="checkbox"/>					
Exhaust System	VI/3	<input checked="" type="checkbox"/>					
Registration No./VIN No.		<input checked="" type="checkbox"/>					
Vehicle Structure	VI/5	<input checked="" type="checkbox"/>					
View of Road		<input checked="" type="checkbox"/>					

No: 43339
 ALF WALSH AUTO ENG'R LTD
 CLEVELAND ST./POOL ST.
 BIRKENHEAD
 Tel: 0151 666 6625

W.B.C. VEHICLE PASS

Ⓢ Damage N/S outer sll.

Petrol Exhaust Emissions			I certify that I have read and understood the above defects and advised same, which are or may become defective before the next MOT or service is due.	Customer's name C. Kelly
Reading	Pass	Fail		Customer's address 27, WALBY CLOX WOODchurch
CO				CH49-7ND
HC			Customer's signature C Kelly	Tel. no. 0151 641 0656
Diesel Exhaust Emissions			Date of test 04.10.09	
Reading	Pass	Fail	Tester's signature [Signature]	