

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE



AA382942
6 MTH
164-190 Cleveland Street
Birkenhead, Merseyside
CH41 3QQ
Tel: 0151-647 5131
Fax: 0151-666 2631

MOT REPORT

Test Centre No. 43339

Reg. No.	Y513 MJH	Make/Model	Peugeot	cc		Year of Manufacture	2000	Class of Vehicle	PH III IV VII	
VIN or Chassis	VF38ERHYF81324327		Recorded Mileage	126394	Colour	Red		<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only						
Lighting Equipment				PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED						
Front & Rear Lamps	1/1			ALF WALSH AUTO ENGR LTD No: 43339 CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625						
Headlamps	1/2									
Headlamp Aim	1/6									
Stop Lamps	1/3									
Rear Reflectors	1/4									
Direction Indicators	1/5			W.B.C. VEHICLE PASS PH AS						
Steering & Suspension										
Steering Control	II/1									
Steering Mechanism/system	II/2									
Power Steering	II/3									
Transmission Shafts	II/2,4,8									
Wheel Bearings	II/4									
Front Suspension	II/5-9									
Rear Suspension	II/9									
Shock Absorbers	II/10									
Wheel Alignment	N/A									
Brakes				W.B.C. VEHICLE PASS PH AS						
Controls	III/1,3									
Condition of Service Brake System	III/3,4									
Condition of Parking Brake System	III/1,2									
Service Brake Performance	III/5,8									
Parking Brake Performance	III/5,8			W.B.C. VEHICLE PASS PH AS						
Tyres & Wheels										
Tyre Type	IV/1									
Tyre Load/Speed Rating (Class VII)										
Tyre Condition	IV/1			W.B.C. VEHICLE PASS PH AS						
Road Wheels	N/2									
Seat Belts										
Mountings	V/1			W.B.C. VEHICLE PASS PH AS						
Condition	V/1									
Operation	V/1									
Vehicle Weight				N/S	O/S	Totals	Balance	Requirement	% Efficient	
Brake Efficiency	Front Brakes			462	521					
	Rear Brakes			139	149					
	Hand Brake			219	264					
General				W.B.C. VEHICLE PASS PH AS						
Windscreen Wipers & Washers	VI/1,2									
Horn	VI/4									
Exhaust System	VI/3									
Registration No./VIN No.										
Vehicle Structure	VI/5			W.B.C. VEHICLE PASS PH AS						
View of Road										
Petrol Exhaust Emissions										
Reading	Pass	Fail	I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.							
CO										
HC										
Diesel Exhaust Emissions				Customer's name: JOHN CHARLTON Customer's address: 46 MAGAZINE LANE, WALLASE WIRRAL CH45-1LU Date of test: _____ Tester's signature: _____ Tel. no: 0151-638-9120						
Reading	Pass	Fail								