


WALSH AUTO ENGINEERING

LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

AA382869



164-190 Cleveland Street
 Birkenhead, Merseyside
 CH41 3QQ
 Tel: 0151-647 5131
 Fax: 0151-666 2631

MOT REPORT

Test Centre No. 43339

Reg. No. X4HSBDF	Make/Model FORD MONDEO	Year of Manufacture 2000	Class of Vehicle PH III IV VII
VIN of Chassis WFO5XXGBB57142873	Colour BLACK	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

ITEMS TESTED	Cars/LGV	Pass	Fail
Lighting Equipment			
Front & Rear Lamps	1/1	-	
Headlamps	1/2	-	
Headlamp Aim	1/6	-	
Stop Lamps	1/3	-	
Rear Reflectors	1/4	-	
Direction Indicators	1/5	-	
Steering & Suspension			
Steering Control	II/1	-	
Steering Mechanism/system	II/2	-	
Power Steering	II/3	-	
Transmission Shafts	II/2,4,9	-	
Wheel Bearings	II/4	-	
Front Suspension	II/5-9	-	
Rear Suspension	II/9	-	
Shock Absorbers	II/10	-	
Wheel Alignment	N/A	N/A	
Brakes			
Controls	III/1,3	-	
Condition of Service Brake System	III/3,4	-	
Condition of Parking Brake System	III/1,2	-	
Service Brake Performance	III/5,8	-	
Parking Brake Performance	III/5,8	-	
Tyres & Wheels			
Tyre Type	IV/1	-	
Tyre Load/Speed Rating (Class VII)		N/A	
Tyre Condition	IV/1	-	
Road Wheels	IV/2	-	
Seat Belts			
Mountings	V/1	-	
Condition	V/1	-	
Operation	V/1	-	
Vehicle Weight			
		N/S	O/S
Brake Efficiency			
Front Brakes			
Rear Brakes			
Hand Brake			
General			
Windscreen Wipers & Washers	VI/1,2	-	
Horn	VI/4	-	
Exhaust System	VI/3	-	
Registration No./VIN No.		-	
Vehicle Structure	VI/5	-	
View of Road		-	

Result of Inspection: Items marked * advisory only

PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED

No: 43339

ALF WALSH AUTO ENG'R LTD
 CLEVELAND ST./POOL ST.
 BIRKENHEAD
 Tel: 0151 666 6625

W.B.C. VEHICLE PASS

N/S	O/S	Totals	Balance	Requirement	% Efficient
			P/H	A/C	

Petrol Exhaust Emissions		
Reading	Pass	Fail
CO		
HC		
Diesel Exhaust Emissions		
Reading	Pass	Fail

I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.

Customer's signature: *[Signature]*

Date of test: **18/08/09**

Tester's signature: *[Signature]*

Customer's name: **E L ROBINSON**

Customer's address: **1 THE CRESCENT PENBY WIRRAL CH61 9QD**

Tel. no.: