

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

Cert No. WA383985



6 MTH

164-190 Cleveland Street
Birkenhead, Merseyside
CH41 3QQ

Tel: 0151-647 5131
Fax: 0151-666 2631

MOT REPORT

6 Months Test 12 Months Test

Plate No. 12 ~~123~~ 05, 10

Reg. No. x696 HNA	Make/Model Ford Mondeo	cc	Year of Manufacture 99	Class of Vehicle PH <input checked="" type="checkbox"/> H <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>
VIN or Chassis WF05XXCBB5YS744G7	Recorded Mileage 207487	Colour Red		

ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only																								
Lighting Equipment				PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED																								
Front & Rear Lamps	1/1	<input checked="" type="checkbox"/>																										
Headlamps	1/2	<input checked="" type="checkbox"/>																										
Headlamp Aim	1/6	<input checked="" type="checkbox"/>																										
Stop Lamps	1/3	<input checked="" type="checkbox"/>																										
Rear Reflectors	1/4	<input checked="" type="checkbox"/>		No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625																								
Direction Indicators	1/5	<input checked="" type="checkbox"/>																										
Steering & Suspension																												
Steering Control	II/1	<input checked="" type="checkbox"/>																										
Steering Mechanism/system	II/2	<input checked="" type="checkbox"/>																										
Power Steering	II/3	<input checked="" type="checkbox"/>																										
Transmission Shafts	II/2,4,9	<input checked="" type="checkbox"/>																										
Wheel Bearings	II/4	<input checked="" type="checkbox"/>																										
Front Suspension	II/5-9	<input checked="" type="checkbox"/>																										
Rear Suspension	II/9	<input checked="" type="checkbox"/>																										
Shock Absorbers	II/10	<input checked="" type="checkbox"/>																										
Wheel Alignment	N/A	<input checked="" type="checkbox"/>																										
Brakes				W.B.C. VEHICLE PASS																								
Controls	III/1,3	<input checked="" type="checkbox"/>																										
Condition of Service Brake System	III/3,4	<input checked="" type="checkbox"/>																										
Condition of Parking Brake System	III/1,2	<input checked="" type="checkbox"/>																										
Service Brake Performance	III/5,8	<input checked="" type="checkbox"/>																										
Parking Brake Performance	III/5,8	<input checked="" type="checkbox"/>																										
Tyres & Wheels				P/H A/C																								
Tyre Type	IV/1	<input checked="" type="checkbox"/>																										
Tyre Load/Speed Rating (Class VII)		<input checked="" type="checkbox"/>																										
Tyre Condition	IV/1	<input checked="" type="checkbox"/>																										
Road Wheels	IV/2	<input checked="" type="checkbox"/>																										
Seat Belts																												
Mountings	V/1	<input checked="" type="checkbox"/>																										
Condition	V/1	<input checked="" type="checkbox"/>																										
Operation	V/1	<input checked="" type="checkbox"/>																										
Vehicle Weight																												
Brake Efficiency				<table border="1"> <thead> <tr> <th>N/S</th> <th>O/S</th> <th>Totals</th> <th>Balance</th> <th>Requirement</th> <th>% Efficient</th> </tr> </thead> <tbody> <tr> <td>Front Brakes</td> <td>701</td> <td>693</td> <td>4</td> <td>50</td> <td>96</td> </tr> <tr> <td>Rear Brakes</td> <td>47</td> <td>45</td> <td>4</td> <td>167</td> <td>37</td> </tr> <tr> <td>Hand Brake</td> <td>269</td> <td>269</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	N/S	O/S	Totals	Balance	Requirement	% Efficient	Front Brakes	701	693	4	50	96	Rear Brakes	47	45	4	167	37	Hand Brake	269	269			
N/S	O/S	Totals	Balance	Requirement	% Efficient																							
Front Brakes	701	693	4	50	96																							
Rear Brakes	47	45	4	167	37																							
Hand Brake	269	269																										
General																												
Windscreen Wipers & Washers	VI/1,2	<input checked="" type="checkbox"/>																										
Horn	VI/4	<input checked="" type="checkbox"/>																										
Exhaust System	VI/3	<input checked="" type="checkbox"/>																										
Registration No./VIN No.		<input checked="" type="checkbox"/>																										
Vehicle Structure	VI/5	<input checked="" type="checkbox"/>																										
View of Road		<input checked="" type="checkbox"/>																										

Petrol Exhaust Emissions Reading Pass Fail CO HC			I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due. Customer's signature: <i>[Signature]</i> Date of test: <i>10.09.10</i> Tester's signature: <i>[Signature]</i>	Customer's name: <i>P. Rowden</i> Customer's address: <i>7A LARCHWOOD CO PENYBRY</i> Tel. no.: <i>0161 634188</i>
Diesel Exhaust Emissions Reading Pass Fail				