

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

Cert No. **WAB383957**



164-190 Cleveland Street
Birkenhead, Merseyside
CH41 3QQ

Tel: 0151-647 5131
Fax: 0151-666 2631

Diesel

MOT REPORT

6 Months Test 12 Months Test

Plate No. **269 31 MAY 2010**

Reg. No. X729 TUA	Make/Model Peugeot 406	cc —	Year of Manufacture 2000	Class of Vehicle PH <input checked="" type="checkbox"/> H <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>
VIN or Chassis VF38BRHZF81253743	Recorded Mileage 20242	Colour Black		

ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only																																			
Lighting Equipment																																							
Front & Rear Lamps	1/1	/		PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED																																			
Headlamps	1/2	/																																					
Headlamp Aim	1/6	/																																					
Stop Lamps	1/3	/																																					
Rear Reflectors	1/4	/																																					
Direction Indicators	1/5	/																																					
Steering & Suspension																																							
Steering Control	II/1	/		ⓐ 075N5K Ant: roll bar links worn																																			
Steering Mechanism/system	II/2	/																																					
Power Steering	II/3	/																																					
Transmission Shafts	II/2,4,9	/																																					
Wheel Bearings	II/4	/																																					
Front Suspension	II/5-9	/																																					
Rear Suspension	II/9	/																																					
Shock Absorbers	II/10	/																																					
Wheel Alignment	N/A	/																																					
Brakes																																							
Controls	III/1,3	/		No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625																																			
Condition of Service Brake System	III/3,4	/																																					
Condition of Parking Brake System	III/1,2	/																																					
Service Brake Performance	III/5,8	/																																					
Parking Brake Performance	III/5,8	/																																					
Tyres & Wheels																																							
Tyre Type	IV/1	/		W.B.C. VEHICLE PASS																																			
Tyre Load/Speed Rating (Class VII)		/																																					
Tyre Condition	IV/1	/																																					
Road Wheels	IV/2	/																																					
Seat Belts																																							
Mountings	V/1	/		P/H A/C																																			
Condition	V/1	/																																					
Operation	V/1	/																																					
Vehicle Weight 1480kg				<table border="1"> <thead> <tr> <th></th> <th>N/S</th> <th>O/S</th> <th>Totals</th> <th>Balance</th> <th>Requirement</th> <th>% Efficient</th> </tr> </thead> <tbody> <tr> <td>Brake Efficiency</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Front Brakes</td> <td>330</td> <td>378</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Rear Brakes</td> <td>252</td> <td>212</td> <td>X</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Hand Brake</td> <td>350</td> <td>305</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		N/S	O/S	Totals	Balance	Requirement	% Efficient	Brake Efficiency							Front Brakes	330	378					Rear Brakes	252	212	X				Hand Brake	350	305				
	N/S	O/S	Totals		Balance	Requirement	% Efficient																																
Brake Efficiency																																							
Front Brakes	330	378																																					
Rear Brakes	252	212	X																																				
Hand Brake	350	305																																					
General																																							
Windscreen Wipers & Washers	VI/1,2	/																																					
Horn	VI/4	/																																					
Exhaust System	VI/3	/																																					
Registration No./VIN No.																																							
Vehicle Structure	VI/5	/																																					
View of Road		/																																					

Petrol Exhaust Emissions			<p>I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.</p> <p>Customer's name W S PIERCY</p> <p>Customer's address 37 BOSWELL RD PRENTON CH43 30A</p> <p>Customer's signature <i>[Signature]</i></p> <p>Date of test 01st MAY 2010</p> <p>Tester's signature <i>[Signature]</i></p> <p>Tel. no. 0151 666 6625</p>
Reading	Pass	Fail	
CO	/		
HC	/		
Diesel Exhaust Emissions			
Reading	Pass	Fail	
	/		