

MANNING'S


QUALITY VEHICLES

ADDRESS: 28 OAKES STREET, LIVERPOOL, L3 5PA

TEL: 0151 709-5009

FAX: 0151 707-8600

VAT NO:



9/4/10

Dear Margaret,

I am writing as per your instructions, to confirm our wish to Winal plate vehicle BX 55 XTD.

As I explained in our telephone conversation the vehicle was financed by ourselves and sold to M^{rs} MATTHEW ROSE, unfortunately M^{rs} ROSE took very ill and was unable to continue with the hire-purchase agreement, and so the vehicle reverted to ourselves for resale.

I enclose copy of WBC vehicle pass, indicating the vehicle was passed before expiry date of old plate.

Yours faithfully

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

Cert No. WA383521



Retail Motor Industry Federation

164-190 Cleveland Street
Birkenhead, Merseyside
CH41 3QQ
Tel: 0151-647 5131
Fax: 0151-666 2631

MOT REPORT

☐ 6 Months Test ☒ 12 Months Test

Plate No. 322 3/2/10

Reg. No. BX55 XTD	Make/Model FIAT	cc —	Year of Manufacture 2006	Class of Vehicle PH H IV VII <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
VIN or Chassis ZFAA2000086160104	Recorded Mileage 133598	Colour Yellow		
ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only
Lighting Equipment				PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED
Front & Rear Lamps	1/1	—		<p>No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625</p>
Headlamps	1/2	—		
Headlamp Aim	1/6	—		
Stop Lamps	1/3	—		
Rear Reflectors	1/4	—		
Direction Indicators	1/5	—		
Steering & Suspension				
Steering Control	II/1	—		
Steering Mechanism/system	II/2	—		
Power Steering	II/3	—		
Transmission Shafts	II/2,4,9	—		<p>W.B.C. VEHICLE PASS</p> <p>P/H A/C</p>
Wheel Bearings	II/4	—		
Front Suspension	II/5-9	—		
Rear Suspension	II/9	—		
Shock Absorbers	II/10	—		
Wheel Alignment	N/A	N/A		
Brakes				
Controls	III/1,3	—		
Condition of Service Brake System	III/3,4	—		
Condition of Parking Brake System	III/1,2	—		
Service Brake Performance	III/5,8	—		<p>N/S O/S Totals Balance Requirement % Efficient</p> <p>Front Brakes</p> <p>Rear Brakes</p> <p>Hand Brake</p>
Parking Brake Performance	III/5,8	—		
Tyres & Wheels				
Tyre Type	IV/1	—		
Tyre Load/Speed Rating (Class VII)		N/A		
Tyre Condition	IV/1	—		
Road Wheels	IV/2	—		
Seat Belts				
Mountings	V/1	—		
Condition	V/1	—		
Operation	V/1	—		
Vehicle Weight				<p>General</p> <p>Windscreen Wipers & Washers VI/1,2 —</p> <p>Horn VI/4 —</p> <p>Exhaust System VI/3 —</p> <p>Registration No./VIN No. —</p> <p>Vehicle Structure VI/5 —</p> <p>View of Road —</p>
Brake Efficiency				
Petrol Exhaust Emissions				<p>I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.</p> <p>Customer's name G. June</p> <p>Customer's address 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100</p> <p>Customer's signature [Signature]</p> <p>Date of test 1.2.2-10</p> <p>Tester's signature [Signature]</p> <p>Tel. no. 0151 666 6625</p>
Reading Pass Fail				
CO				
HC				
Diesel Exhaust Emissions				
Reading Pass Fail				