

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE

WA384714



164-190 Cleveland Street
Birkenhead, Merseyside
CH41 3QQ

Tel: 0151-647 5131

Fax: 0151-666 2631

MOT REPORT

Test Centre No. 43339

Reg. No. SWS1 AVO	Make/Model Vauxhall	cc N/A	Year of Manufacture 2001	Class of Vehicle PH <input checked="" type="checkbox"/> III <input type="checkbox"/> IV <input type="checkbox"/> VII																																						
VIN or Chassis WJDL0T9F482801S954		Recorded Mileage 20478	Colour BLUE	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>																																						
ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only																																						
Lighting Equipment				PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED																																						
Front & Rear Lamps	1/1	-		<p>No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625</p>																																						
Headlamps	1/2	-																																								
Headlamp Aim	1/6	-																																								
Stop Lamps	1/3	-																																								
Rear Reflectors	1/4	-																																								
Direction Indicators	1/5	-																																								
Steering & Suspension																																										
Steering Control	II/1	-																																								
Steering Mechanism/system	II/2	-																																								
Power Steering	II/3	-																																								
Transmission Shafts	II/2,4,9	-																																								
Wheel Bearings	II/4	-																																								
Front Suspension	II/5-9	-																																								
Rear Suspension	II/9	-																																								
Shock Absorbers	II/10	-																																								
Wheel Alignment	N/A	N/A																																								
Brakes				<p>W.B.C. VEHICLE PASS</p>																																						
Controls	III/1,3	-																																								
Condition of Service Brake System	III/3,4	-																																								
Condition of Parking Brake System	III/1,2	-																																								
Service Brake Performance	III/5,8	-																																								
Parking Brake Performance	III/5,8	-																																								
Tyres & Wheels				<p>P/H A/C</p>																																						
Tyre Type	IV/1	-																																								
Tyre Load/Speed Rating (Class VII)		N/A																																								
Tyre Condition	IV/1	-																																								
Road Wheels	IV/2	-																																								
Seat Belts				<table border="1"> <thead> <tr> <th>Vehicle Weight</th> <th>N/S</th> <th>O/S</th> <th>Totals</th> <th>Balance</th> <th>Requirement</th> <th>% Efficient</th> </tr> </thead> <tbody> <tr> <td>Brake Efficiency</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Front Brakes</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Rear Brakes</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Hand Brake</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				Vehicle Weight	N/S	O/S	Totals	Balance	Requirement	% Efficient	Brake Efficiency							Front Brakes							Rear Brakes							Hand Brake						
Vehicle Weight	N/S	O/S	Totals					Balance	Requirement	% Efficient																																
Brake Efficiency																																										
Front Brakes																																										
Rear Brakes																																										
Hand Brake																																										
Mountings	V/1	-																																								
Condition	V/1	-																																								
Operation	V/1	-																																								
General				<table border="1"> <thead> <tr> <th>Reading</th> <th>Pass</th> <th>Fail</th> </tr> </thead> <tbody> <tr> <td>Petrol Exhaust Emissions</td> <td></td> <td></td> </tr> <tr> <td>CO</td> <td></td> <td></td> </tr> <tr> <td>HC</td> <td></td> <td></td> </tr> <tr> <td>Diesel Exhaust Emissions</td> <td></td> <td></td> </tr> <tr> <td>Reading</td> <td>Pass</td> <td>Fail</td> </tr> </tbody> </table>				Reading	Pass	Fail	Petrol Exhaust Emissions			CO			HC			Diesel Exhaust Emissions			Reading	Pass	Fail																	
Reading	Pass	Fail																																								
Petrol Exhaust Emissions																																										
CO																																										
HC																																										
Diesel Exhaust Emissions																																										
Reading	Pass	Fail																																								
Windscreen Wipers & Washers	VI/1,2	-																																								
Horn	VI/4	-																																								
Exhaust System	VI/3	-																																								
Registration No./VIN No.		-																																								
Vehicle Structure	VI/5	-																																								
View of Road		-																																								
Petrol Exhaust Emissions		I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.		Customer's name M LANSDALE																																						
Reading	Pass	Fail	Customer's signature <i>[Signature]</i> Date of test <i>[Signature]</i> Tester's signature <i>[Signature]</i>	Customer's address 932 CHESTER RD																																						
CO				GREAT SUTTON																																						
HC				CH66 2LT																																						
Diesel Exhaust Emissions				Tel. no 074694 501232																																						
Reading	Pass	Fail																																								