


# WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE



164-190 Cleveland Street  
Birkenhead, Merseyside  
CH41 3QQ  
Tel: 0151-647 5131  
Fax: 0151-666 2631

## MOT REPORT

764 5 Sep 2010  
Test Centre No. 43339

Reg. No. <b>JS AYP</b>	Make/Model <b>Audi A6</b>	cc <b>—</b>	Year of Manufacture <b>2002</b>	Class of Vehicle PH <input checked="" type="checkbox"/> III <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>			
VIN or Chassis <b>WAUZZZ4B7ZNO86519</b>	Recorded Mileage <b>225909</b>	Colour <b>Silver</b>					
<b>ITEMS TESTED</b>	Cars/LGV	Pass	Fail	<b>Result of inspection: Items marked * advisory only</b>			
<b>Lighting Equipment</b>				<b>PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED</b>			
Front & Rear Lamps	I/1	/					
Headlamps	I/2	/					
Headlamp Aim	I/6	/					
Stop Lamps	I/3	/					
Rear Reflectors	I/4	/					
Direction Indicators	I/5	/					
<b>Steering &amp; Suspension</b>				<p>No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625</p>			
Steering Control	II/1	/					
Steering Mechanism/system	II/2	/					
Power Steering	II/3	/					
Transmission Shafts	II/2,4,9	/					
Wheel Bearings	II/4	/		<p><b>W.B.C. VEHICLE PASS</b></p>			
Front Suspension	II/5-9	/					
Rear Suspension	II/9	/					
Shock Absorbers	II/10	/					
Wheel Alignment	N/A						
<b>Brakes</b>				<p><b>P/H A/C</b></p>			
Controls	III/1,3	/					
Condition of Service Brake System	III/3,4	/					
Condition of Parking Brake System	III/1,2	/					
Service Brake Performance	III/5,8	/					
Parking Brake Performance	III/5,8	/					
<b>Tyres &amp; Wheels</b>							
Tyre Type	IV/1	/					
Tyre Load/Speed Rating (Class VII)							
Tyre Condition	IV/1	/					
Road Wheels	IV/2	/					
<b>Seat Belts</b>							
Mountings	V/1	/					
Condition	V/1	/					
Operation	V/1	/					
<b>Vehicle Weight</b>							
<b>Brake Efficiency</b>							
	Front Brakes	N/S	0/8	Totals	Balance	Requirement	% Efficient
	Rear Brakes	516	584			50	93
	Hand Brake	179	173			16	48
		366	389				
<b>General</b>							
Windscreen Wipers & Washers	VI/1,2	/					
Horn	VI/4	/					
Exhaust System	VI/3	/					
Registration No./VIN No.							
Vehicle Structure	VI/5	/					
View of Road							
<b>Petrol Exhaust Emissions</b>							
Reading	Pass	Fail					
CO	/						
HC	/						
<b>Diesel Exhaust Emissions</b>							
Reading	Pass	Fail					
	/						
I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due.				Customer's name <b>J.P. WHEADON</b>			
Customer's signature <i>[Signature]</i>				Customer's address <b>62 TEEHEY LANE</b>			
Date of test <b>26th August 2010</b>				Customer's address <b>HIGHER BEBINGSTON</b>			
Tester's signature <i>[Signature]</i>				Tel. no. ....			