

WALSH AUTO ENGINEERING LTD.

ACCIDENT REPAIR CENTRE MOT TEST CENTRE FAST-FIT CENTRE



164-160 Cleveland Street
 Birkenhead, Merseyside
 CH41 3QG
 Tel: 0151-647 5131
 Fax: 0151-666 2631

MOT REPORT

Test Centre No. 43339

854 18, 09, 10

Reg. No. BK02 SWZ	Make/Model V.W Passat	cc cc	Year of Manufacture 02	Class of Vehicle PH <input type="checkbox"/> III <input type="checkbox"/> IV <input type="checkbox"/> VII <input type="checkbox"/>																																						
VIN or Chassis WVWZ223BZP344114	Recorded Mileage 161014	Colour Silver	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>																																							
ITEMS TESTED	Cars/LGV	Pass	Fail	Result of Inspection: Items marked * advisory only																																						
Lighting Equipment				PLEASE PRODUCE THIS FORM IF A RE-TEST IS REQUIRED																																						
Front & Rear Lamps	1/1	<input checked="" type="checkbox"/>																																								
Headlamps	1/2	<input checked="" type="checkbox"/>																																								
Headlamp Aim	1/6	<input checked="" type="checkbox"/>																																								
Stop Lamps	1/3	<input checked="" type="checkbox"/>																																								
Rear Reflectors	1/4	<input checked="" type="checkbox"/>																																								
Direction Indicators	1/5	<input checked="" type="checkbox"/>																																								
Steering & Suspension																																										
Steering Control	II/1	<input checked="" type="checkbox"/>																																								
Steering Mechanism/system	II/2	<input checked="" type="checkbox"/>																																								
Power Steering	II/3	<input checked="" type="checkbox"/>																																								
Transmission Shafts	II/2,4,9	<input checked="" type="checkbox"/>																																								
Wheel Bearings	II/4	<input checked="" type="checkbox"/>																																								
Front Suspension	II/5-9	<input checked="" type="checkbox"/>																																								
Rear Suspension	II/9	<input checked="" type="checkbox"/>																																								
Shock Absorbers	II/10	<input checked="" type="checkbox"/>																																								
Wheel Alignment	N/A	<input checked="" type="checkbox"/>																																								
Brakes				No: 43339 ALF WALSH AUTO ENG'R LTD CLEVELAND ST./POOL ST. BIRKENHEAD Tel: 0151 666 6625																																						
Controls	III/1,3	<input checked="" type="checkbox"/>																																								
Condition of Service Brake System	III/3,4	<input checked="" type="checkbox"/>																																								
Condition of Parking Brake System	III/1,2	<input checked="" type="checkbox"/>																																								
Service Brake Performance	III/5,8	<input checked="" type="checkbox"/>																																								
Parking Brake Performance	III/5,8	<input checked="" type="checkbox"/>		W.B.C. VEHICLE PASS																																						
Tyres & Wheels																																										
Tyre Type	IV/1	<input checked="" type="checkbox"/>																																								
Tyre Load/Speed Rating (Class VII)	IV/1	<input checked="" type="checkbox"/>																																								
Road Wheels	IV/2	<input checked="" type="checkbox"/>																																								
Seat Belts				<table border="1"> <thead> <tr> <th>Vehicle Weight</th> <th>N/S</th> <th>O/S</th> <th>Totals</th> <th>Balance</th> <th>Requirement</th> <th>% Efficient</th> </tr> </thead> <tbody> <tr> <td>Brake Efficiency</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Front Brakes</td> <td>459</td> <td>617</td> <td></td> <td></td> <td></td> <td>98</td> </tr> <tr> <td>Rear Brakes</td> <td>243</td> <td>251</td> <td></td> <td></td> <td></td> <td>52</td> </tr> <tr> <td>Hand Brake</td> <td>390</td> <td>369</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				Vehicle Weight	N/S	O/S	Totals	Balance	Requirement	% Efficient	Brake Efficiency							Front Brakes	459	617				98	Rear Brakes	243	251				52	Hand Brake	390	369				
Vehicle Weight	N/S	O/S	Totals					Balance	Requirement	% Efficient																																
Brake Efficiency																																										
Front Brakes	459	617								98																																
Rear Brakes	243	251								52																																
Hand Brake	390	369																																								
Mountings	V/1	<input checked="" type="checkbox"/>																																								
Condition	V/1	<input checked="" type="checkbox"/>																																								
Operation	V/1	<input checked="" type="checkbox"/>																																								
General																																										
Windscreen Wipers & Washers	VI/1,2	<input checked="" type="checkbox"/>																																								
Horn	VI/4	<input checked="" type="checkbox"/>																																								
Exhaust System	VI/3	<input checked="" type="checkbox"/>																																								
Registration No./VIN No.		<input checked="" type="checkbox"/>																																								
Vehicle Structure	VI/5	<input checked="" type="checkbox"/>																																								
View of Road		<input checked="" type="checkbox"/>																																								
Petrol Exhaust Emissions								I certify that I have read and understood the above defects and advised items, which are or may become defective before the next MOT or service is due. Customer's name: BARRY SEVENS Customer's address: 8 WELLINGTON RD WALLASEY WIRRAL CH45 2PN Tel. no: 07825017801																																		
Reading	Pass	Fail																																								
CO																																										
HC																																										
Diesel Exhaust Emissions																																										
Reading	Pass	Fail		Date of test: 23, 08, 10 Tester's signature: [Signature]																																						
CO																																										